



SURF PREP

Product Data Sheet



SOLAR SURF PREP is designed to dissolve and remove dirt, oil and grease from surfaces to promote the best adhesion of paints or coatings without the use of solvents.

SOLAR SURF PREP was specifically designed to clean aluminum and other metal surfaces prior to painting, but is also effective on any other surface. The product works like a soft abrasive to remove contaminants from surfaces.

- **Removes Dirt, Oil and Grease**
- **Non-Solvent**
- **Preps Surface for Best Adhesion of Paints and Coatings**
- **Acts like a soft abrasive**

DIRECTIONS: Always follow the Precautionary Statements. SOLAR SURF PREP can be diluted up to 1-3 times with water, depending on the surface condition to be treated. Test in a small area to determine compatibility and results. Apply the solution with a brush, roller, mop or low-pressure sprayer. If surface is hot, wet before applying cleaner solution. Leave SOLAR SURF PREP on surface for 5-10 minutes, but do not allow the surface to dry. Rinse the surface with large amounts of water. For large surfaces, rinsing with a power washer is recommended. All product must be removed. Allow the surface to dry thoroughly before applying any coatings.

Do not apply the solution to glass surfaces, metallic automobile finishes, aluminum surfaces which will remain unpainted or strong alkali sensitive painted surfaces.

For Industrial or Professional Use Only. Keep out of reach of children.